

The Commonwealth of Massachusetts

Executive Office of Environmental Affairs Department of Environmental Quality Engineering Southeast Region

Lakeville Hospital, Lakeville, Massachusetts 02347

947-1231. Ext. 680-684

March 10, 1988



Mr. John J. Bailey, Jr. Acushnet Company Rubber Division, Plant B P.O. Box E-916

New Bedford, Massachusetts 02742

RE: NEW BEDFORD-Water Pollution Control--Acushnet Company, Rubber Division, NPDES #MA0003913, Cooling Water Discharge, Industrial

Minor

Dear Mr. Bailey:

The Department of Environmental Quality Engineering has had an engineer from this office conduct an inspection of your cooling water discharge on March 1, 1988.

The purpose of the above-noted inspection was to verify compliance with your NPDES permit requirements and 314 CMR 12.00: "Operation and Maintenance and Pretreatment Standards for Wastewater Treatment Works and Indirect Dischargers."

In addition to a representative from this office, Robert H. Richards, Environmental Compliance Engineer for your facility was also present during the inspection.

The inspection revealed no major deficiencies or violations and a review of the facility's records indicates that the plant is adequately achieving compliance with the parameter limits.

If there are any questions relative to the above, please feel free to contact Judith L. Kronenberg of my staff at the above telephone number.

Very truly yours,

iution Control Section

G/JLK/lm

cc: DEOE - DWPC

Permits Section, 7th Floor Inspection Fee Program ATTN: Glen Gilmore

cc: U.S. EPA
Water Compliance Section
JFK Federal Building
Boston, MA 02203
ATTN: Mark Robertson